Voluntary Product Recall

Liebherr Built-In 30-Inch Wide Refrigerators

The doors of certain models of Liebherr refrigerators can detach, posing an injury hazard to consumers.

The recall involves certain models **C 1600, C 1601, C 1650, C 1651, CI 1600, CI 1650, CI 1651** and **CI 1700**. Models sold with specific index numbers are subject to the recall. These 30-inch wide bottom freezer refrigerators come individually or as side-by-side combinations in models **SBS 320** and **SBS 32I0**. The affected units were sold between **February 2004** and **January 2011**.



1 **Model and Index Number**

The refrigerators come in stainless steel and various custom finishes. “Liebherr” is written on the top interior control panel. The model & index numbers are located on the serial tag on the behind the bottom produce drawer on the left interior side of the refrigerators.

To determine if your refrigerator is included in this recall or to schedule a free in-home repair please call or visit:

In the USA: **1-877-337-2653** Monday – Friday, 8 a.m. to 5 p.m. (Mountain Time)
In Canada: 1**-888-543-2437** Monday – Friday, 8 a.m. to 5 p.m. (Eastern Time)

www.liebherr.us / www.liebherr.ca
Click **Recall Information** under **Smartlinks**

Post until June 30, 2011

In Cooperation with the U.S. Consumer Product Safety Commission