



Date:	October 18, 2013
To:	Sales Team, Customer Care Representatives & Product Data Group
From:	Jennifer Goff
Re:	Outlook Plus Price Book and Technical Drawing Corrections

AKER

AKER PRICE BOOK CORRECTION

Take note of the following corrections to your Aker Outlook Plus price book and the Aker Website:


Products Affected: Aker Outlook Plus Reduced Skirt Units

Corrections:

- **Page 12:** The drawing for the 3/4" reduced skirt unit is incorrect. The Aker Outlook Plus reduced skirt units DO have a flange. It is there to provide strength to the unit and prevent warping.
- **Pages 21, 27, 34:** All drawings for "RS" (reduced skirt) units that are provided after each product page are also incorrect.
- **NOTE:** you cannot order the RS unit without a skirt


Updated Information:

- **Website:** The technical drawings, builder specs and submittal sheets have all been updated on line.
- **Price Guide:** The electronic price guide in the MAAAX brand center is 100% updated.




Details:

INCORRECT FLANGE DRAWING



CORRECT FLANGE DRAWING



Please contact me should you have any questions or concerns.

Best,

Jennifer Goff

U.S. Director of Marketing