

**California Faucets Catalog Errata Sheet**

March 2017

SKU	page #	incorrect	correct	notes
45-RH	115	97/131/156	110/148/175	
72-RH	275	97/131/156	110/148/175	
H-71 handle option	276	Noted as CROSS	Should be LEVER	
TO-7403L	289	393/531/629	393/531/630	
TO-THF2L-74	295	497/646/795	497/671/795	
TO-THFN-77	303 & 313	472/614/755	472/637/755	
TO-THF2L-77	305 & 315	572/744/915	572/772/915	
9206C	308	sku incorrectly labeled 9206	should be 9206C	
TO-VE3202C-7-77R	329	TO-VE3202C	TO-VE302C-7-77R	
E301-2	347	659/890/1024	659/890/1054	pricing is correctly listed as 1054 on page 329
SB-XX	369	missing series	should be: 32, 33, 34, 35, 36, 38, 40, 42, 45, 46, 47, 48, 48X, 50, 51, 55, 59, 60, 63, 64, 67, and 68	
Styleflow Air Hand-showers	372	bullets indicate the sku as SH	"SH" should be corrected to indicate "HS"	
9179-BFP	401	STYLEDRAIN TISTO ROUGH BODY WITH 2"/3" ABS	STYLEDRAIN TISTO ROUGH BODY WITH 2"/3" PVC	
9050Z	414	109/136/174	109/147/174	pricing is correctly listed on page 308 & 318
9053-D	428	bullets are incorrect	* 1-1/4" ODx10" Tailpiece * maximum installation thickness is 4-1/4"	
TS-55-38	433	195/236/312	195/263/363	pricing is correct in other parts of catalog
TS-55-40	433	195/236/313	195/263/364	pricing is correct in other parts of catalog
TS-55-64	433	195/236/314	195/263/365	
TS-E4-E4	435	367/495/587	259/350/414	pricing is correctly listed as 259/350/414 on page 342
TS-77-77	435	195/263/312	259/350/414	pricing is correctly listed on page 427
9221	439	bullets are incorrect	<ul style="list-style-type: none"> <li>• solid brass</li> <li>• includes 9234-faceplate &amp; 9231-drain</li> <li>• 24" max overflow make-up</li> <li>• 12" max waste make-up</li> </ul>	
DDV-R	453	224	229	pricing is correctly listed on each series as \$229
EXT-TH	457	18	195/263/312	
VS-73-9	462	235/317/376	245/331/392	
EB-40	467	35/47/56	38/51/61	
HM-69	472	159/185/203	140/189/223	
H-69	472	159/185/204	140/189/223	
LK-59	473	16/22/26	18/24/29	
65-TP-SN	229	141/191/226	177/239/283	pricing correct on page 221