



PINNACLE

SALES GROUP

Item Class	Item Number	Serial Num	Item Description	Scratch & Dent Notes	Sale Price
ALFRESCO	ALXE-56SZC-LP	22-110073	56" Deluxe Cart Grill, 2 Burner, Side Burner, Rotis, Double Door, Double Dwrr, Sear Zone, LP	Rank A: Scratches inside the grill on the back wall.	\$ 4,999
ALFRESCO	ALXE-56SZ-LP	22-108052	56" Built-In Grill, 2 Burner, Side Burner, Rotis, Sear Zone, LP	Rank B: Dent to power cord box; Deep scratch to the top of control panel; Small bump on right side frame of side burner.	\$ 3,999
ALFRESCO	ALXE-56BFG-LP	22-109128	56" Built-In Grill, 2 Burner + SearZone, Rotis, LP	Rank C: Unit has 2 vertical scrapes to the top of the lid.	\$ 2,999
ALFRESCO	ALXE-36SZ-NG	22-104111	36" Built-In Grill, 2 Burner, Rotis, Sear Zone, NG	Rank B+: Minor scrapes to the hood; Scratches on the left side of unit; Minor scratches to the back of unit; Minor scratches to the firebox frame.	\$ 2,999
ALFRESCO	ALXE-36C-NG	20-83166	36" Cart Model Grill, 2 Burner, Rotis, Double Door, NG	Rank B: Unit has a small dent in the center of the grill.	\$ 2,499
ALFRESCO	ALXE-36SZ-NG	22-106918	36" Built-In Grill, 2 Burner, Rotis, Sear Zone, NG	Rank B: Minor scratches to the lid.	\$ 2,499
ALFRESCO	ALXE-36SZ-NG	22-103041	36" Built-In Grill, 2 Burner, Rotis, Sear Zone, NG	Rank B: Dent in the middle of the right side frame trim.	\$ 2,499

ALFRESCO	ALXE-42SZ-NG	23-118003	42" Built-In Grill, 2 Burner, Rotis, Sear Zone, NG	Rank C: Dented at the top left side of the hood; scratch and dent to the left side of firebox frame; Slightly bowed at both sides of the hood.	\$ 1,999
ALFRESCO	ALXE-36SZ-LP	17-63423	36" Built-In Grill, 2 Burner, Rotis, Sear Zone, LP	Rank B: Unit has rust scratches on the front left side of hood.	\$ 1,999
ALFRESCO	URS-1XE	21-96419	28" Single Door Refrigerator, 7.25 Cubic Ft.	Rank B: Scratch and dent to the left side of the door; Minor scratches to the door handle.	\$ 1,999
ALFRESCO	URS-1XE	21-91720	28" Single Door Refrigerator, 7.25 Cubic Ft.	Rank A: Various stains and scratches to top of unit.	\$ 1,999
ARTISAN	ARTP-PZA-LP	21-87323	Artisan 30" Countertop Pizza Oven, LP	Rank B: Various scratches to the top of the control panel and to the lid of the unit; Minor dents at each corner of unit.	\$ 1,999
ARTISAN	ARTP-32C-LP	21-93755	Professional 32" Cart Model Grill, 3 Burner, Rotis, LP	Rank A: Unit lid is slightly dented on both sides at the hinges.	\$ 1,599
ARTISAN	AAEP-36-LP	23-118816	American Eagle 36" Built-IN Grill, 3 Burner, LP	Rank A: Minor scratch and dent to the back of unit.	\$ 1,299
ARTISAN	ARTP-32-LP	21-90014	Professional 32" Built-IN Grill, 3 Burner, Rotis, LP	Rank B: Minor scratches to the top of the control panel and right and left of the unit.	\$ 1,099
ARTISAN	ARTP-32-LP	18-70259	Professional 32" Built-IN Grill, 3 Burner, Rotis, LP	Rank B: Minor rust stains on front left and right side of the lid.	\$ 1,099
ARTISAN	AAEP-26-LP	20-78220	American Eagle 26" Built-IN Grill, 2 Burner, LP	Rank B: Minor scrapes to the hood.	\$ 799

ARTISAN	ART-BC24	22-99398	24" Outdoor Refrigerator, Stainless Steel, RH Door Swing	Rank B: Unit has multiple scratches to the top and a small dent in the back of unit.	\$ 699
ARTISAN	ARTP-SB2-LP	18-70397	Double Side Burner, Built-IN, LP	Rank A: Minor scratches to item.	\$ 399
ASKO	DOD651PHXXLS	21230028	**Replaced by DOD561TXXLS** 24" Outdoor Dishwasher, XXL Tub, Pro Handle, Stainless	Rank B: Minor dent to the bottom of door towards left corner; Slightly bowed out on the left side of unit.	\$ 1,799
ASKO	DOD561TXXLS	74011031430015	24" Outdoor Dishwasher, XXL Tub, T-Bar Handle, Stainless	Rank A: Unit is dented on both sides.	\$ 1,499
ASKO	DOD561TXXLS	74011031930019	24" Outdoor Dishwasher, XXL Tub, T-Bar Handle, Stainless	B; back left corner crushed	\$ 1,399
ASKO	W4114CW	20630175	24" Washer, Logic, White	Rank B: Scrape and slight dent to right side panel.	\$ 999
ASKO	DFI786XXLSOF	74009431930011	24" Dishwasher, 60+ Series, XXL Tub, Water Softener, Panel Ready	Rank B: Dent on the door's right side from the middle to the bottom of door.	\$ 999
ASKO	T411HSW	73024430630003	24" Heat Pump Dryer, Logic, White	Rank A: Unit has a slight dent on the left side of unit toward the back bottom corner; Slight bump to the left side of the unit.	\$ 999
ASKO	W4114CW	57820515030007	24" Washer, Logic, White	Rank C: Unit is dented on the right side; Scratched at the front right corner of unit; Dent and scratch to the top of unit.	\$ 799
ASKO	DBI675PHXXLS	23630013	24" Dishwasher, 50 Series, XXL Tub, Pro Handle, Stainless	Rank B: Small dent to the door toward the lower right side of the door.	\$ 799

ASKO	DBI675IXXLS	21630142	24" Dishwasher, 50 Series, XXL Tub, Pocket Handle, Stainless	Rank A: Right mounting bracket is bent at top corner.	\$ 799
ASKO	DBI675IXXLS	20430067	24" Dishwasher, 50 Series, XXL Tub, Pocket Handle, Stainless	Rank A: Dent to the back of unit on the right side.	\$ 799
ASKO	DFI776XXLSOF	74009631630107	24" Dishwasher, 60 Series, XXL Tub, Water Softener, Panel Ready	A; back right corner dented. Repair: needs new packaging	\$ 799
ASKO	W4114CW	30930100	24" Washer, Logic, White	Rank C: top left corner and front bottom have deep scratches	\$ 699
ASKO	W2084W	57820630430035	24" Washer, Classic, White	Rank B: Small dent to bottom right side	\$ 699
ASKO	W2084W	57820620531140	24" Washer, Classic, White	Rank B: Paint chipped dent on the lid toward the left side; Minor scratches toward the back left side of lid; Minor dent on top of lid towards the right side.	\$ 699
ASKO	DFI664XXL	21530106	**Replaced by DFI565XXL** 24" Dishwasher, 40 Series, XXL Tub, Panel Ready	Rank A: Scratch to the bottom right side of door.	\$ 699
ASKO	T411VDW	58698131430024	24" Vented Dryer, Logic, White	Rank A: No damage, no box	\$ 699
ASKO	T208CW	58819823430099	24" Condenser Dryer, Classic, White	Rank A: Minor scrape to the front of the unit to the left of the door.	\$ 699
ASKO	DFI664XXL	73704824330993	**Replaced by DFI565XXL** 24" Dishwasher, 40 Series, XXL Tub, Panel Ready	Rank A: Dented at the top towards the back right corner; Slight dent to the top of the door on the right side and a scratch to the door.	\$ 699

ASKO	DFI565XXLSOF	74009930130029	24" Dishwasher, 50 Series, XXL Tub, Water Softener, Panel Ready	Rank A: Paint chipped scratches to the right side of door.	\$ 699
ASKO	DBI664IXXLS	22230222	24" Dishwasher, 40 Series, XXL Tub, Pocket Handle, Stainless	Rank A+: Good condition	\$ 599
ASKO	DBI664IXXLS	21530082	24" Dishwasher, 40 Series, XXL Tub, Pocket Handle, Stainless	Rank A: Multiple scratches to left side door bracket.	\$ 599
ASKO	DBI664IXXLS	73706523630228	24" Dishwasher, 40 Series, XXL Tub, Pocket Handle, Stainless	Rank A: Left side door trim slightly bent.	\$ 599
ASKO	DBI664IXXLS	22230129	24" Dishwasher, 40 Series, XXL Tub, Pocket Handle, Stainless	Rank A: Good condition; Door Panel replaced.	\$ 599
ASKO	DFI776XXLSOF	74009631830017	24" Dishwasher, 60 Series, XXL Tub, Water Softener, Panel Ready	C; frame is bent front bottom	\$ 599
ASKO	DBI663IS	22803557	24" Dishwasher, 30 Series, Pocket Handle, Stainless	Rank A: Replaced door panel.	\$ 499
ASKO	DBI664PHXXLS	22630243	24" Dishwasher, 40 Series, XXL Tub, Pro Handle, Stainless	Rank C: Slight dent to both bottom corners of the door.	\$ 499
ASKO	W2084W	57820622430310	24" Washer, Classic, White	Rank C: front of frame sustained small dents and scratches; is bent. The little door on the front left bottom is smashed.	\$ 499
ASKO	DBI564IS	74010930930371	24" Dishwasher, 40 Series, Pocket Handle, Stainless	Rank B: Unit top frame dented; top left door corner slightly dented; top left door frame is bent.	\$ 499

ASKO	DFI564XXL	74010431330211	24" Dishwasher, 40 Series, XXL Tub, Panel Ready	Rank B: Unit is dented at the top left door frame and door; scrapes to the top left corner of door.	\$ 499
ASKO	DBI664IXXLS	22230081	24" Dishwasher, 40 Series, XXL Tub, Pocket Handle, Stainless	Rank B: Minor scratches to the top left corner of the door; slight dent on the right top corner of frame.	\$ 499
ASKO	DBI663IS	21430404	24" Dishwasher, 30 Series, Pocket Handle, Stainless	Rank A: Door brackets slightly bent on the left side.	\$ 499
ASKO	DFI664XXL	21431439	**Replaced by DFI565XXL** 24" Dishwasher, 40 Series, XXL Tub, Panel Ready	Rank C: Multiple scrapes on the left and right side of the door.	\$ 399
ASKO	DBI663IS	22830537	24" Dishwasher, 30 Series, Pocket Handle, Stainless	Rank B: Minor dent to the left side of the door.	\$ 399
ASKO	DBI663IS	73706124230157	24" Dishwasher, 30 Series, Pocket Handle, Stainless	Rank B: Dented on the left side of the door at the bottom corner.	\$ 399
ASKO	DBI663IS	22630036	24" Dishwasher, 30 Series, Pocket Handle, Stainless	Rank A+: Right side bracket slightly bent.	\$ 399
AZURE	A224R-S	A224R-S27A381	24" Refrigerator with Solid Stainless Door	Rank A: Top of unit and top of door has minor scratches.	\$ 399
AZURE	A224BEV-S	8A224BEV-S1433	24" Beverage Center with Stainless Trim Glass Door	Rank A: Minor dents to the left side of unit; back vent missing top 2 screws.	\$ 399
BREDA	LUDWT30250	73936214530287	24" Tall Tub Pro Dishwasher, Panel Ready	Rank A: Display unit; good condition.	\$ 299
BREDA	LUDWT30250	73936214030043	24" Tall Tub Pro Dishwasher, Panel Ready	Rank B: Scrape to the right side of door.	\$ 199

COYOTE	C1P36-FS	21C1P36FS2493	36" Pellet Grill and Cart	Rank B+: Dent and scratch to the right side of cart; Various minor scratches to the unit.	\$ 1,999
COYOTE	C2SL42LP	21C2SL42LPO786	42" S-Series Grill, LED Lights, Ceramics, LP	Rank B: Damaged drip tray, scratches to the bottom of the control panel, slight dent to the right side of fire box and a slight bump on the left top side of fire box.	\$ 1,899
COYOTE	C2SL42LP	21C2SL42LP1183	42" S-Series Grill, LED Lights, Ceramics, LP	Rank B: Back bottom frame damaged; Minor dents to the lid.	\$ 1,499
COYOTE	C2SL42NG	21C2SL42NG1964	42" S-Series Grill, LED Lights, Ceramics, NG	Rank A: Slight damage to the pull out tray on the left side; slightly dented on the left side of the grill near the pull out tray.	\$ 1,499
COYOTE	C2SL36NG	21C2SL36NG7169	36" S-Series Grill, LED Lights, Ceramics, NG	Rank A: Good Condition. Replaced thermostat.	\$ 1,499
COYOTE	C1P36-FS	20C1P36FS0138	36" Pellet Grill and Cart	Rank C: Various scratches to the hood, shelves and hooper cover; Scrapes to cart drawers.	\$ 1,399
COYOTE	C2SL36NG	21C2SL36NG6529	36" S-Series Grill, LED Lights, Ceramics, NG	Rank A: Dent to the back of grill on the right side and various minor scratches.	\$ 1,299
COYOTE	C2SL36NG	21C2SL36NG7194	36" S-Series Grill, LED Lights, Ceramics, NG	Rank B: Back lower frame bar bent; minor scratches to the hood.	\$ 1,199
COYOTE	C2SL30LP-FS	21C2SL30LP-FS0688	30" S-Series Grill, LED Lights, Ceramics, LP	Rank C: Dented at the left side of the top of the control panel.	\$ 999

COYOTE	C2SL36LP	22C2SL36LP5129	36" S-Series Grill, LED Lights, Ceramics, LP	Rank C: Dent to the front of hood toward upper right corner and lid is slightly bent at the lid screw.	\$ 999
COYOTE	C2C42LP	21C2C42LP0885	42" C-Series Grill, 5 Burner, LP	Rank B: Two wide scratches on left and right of lid and slight dent to the left side of lid within the scratches.	\$ 999
COYOTE	C2SL36LP	22C2SL36LP5644	36" S-Series Grill, LED Lights, Ceramics, LP	Rank B: Slight dent to the top left corner; scratches to the top of control panel in front of grates; inner back wall warmer damaged and drip tray is dented on the bottom.	\$ 999
COYOTE	C2SL30NG	21C2SL30NG1696	30" S-Series Grill, LED Lights, Ceramics, NG	Rank B: Scratches to the top of the hood; Firebox top trim dented on the back left side and right side of unit towards the back.	\$ 999
COYOTE	C2C36LP	22C2C36LP3291	36" C-Series Grill, 4 Burner, LP	Rank B: Multiple scratches to the control panel and a dent to the right side of the drip tray.	\$ 999
COYOTE	C2C42NG	23C2C42NG1648	42" C-Series Grill, 5 Burner, NG	B RIGHT SIDE OFF PRODUCT HINGE PUSHED IN WITH SCREW AND HOOD HAS BEEN BENT.	\$ 999
COYOTE	C2C34NG	21C2C34NG2829	34" C-Series Grill, 3 Burner, NG	Rank B: Slight dent to the top back of lid causing a small bump to the top of lid.	\$ 799
COYOTE	C1FTG30LP	22C1FTG30LP0989	30" Flat Top Grill Built-in, LP	Rank A: Good condition	\$ 799

COYOTE	C1BIR24-R	21C1BIR24-R10894	24" Outdoor Refrigerator, RH	Rank A: Dent to back bottom vent.	\$ 799
COYOTE	C1C28NG-FS	20C1C28NGFS10351	28" C-Series Grill w/Cart, 2 Burner, NG	Rank B+: Small dent to the right side of cart.	\$ 699
COYOTE	C1C28NG-FS	21C1C28NGFS14214	28" C-Series Grill w/Cart, 2 Burner, NG	Rank B: Scratches to the front frame of the firebox; dent on the right side of fire box hood; various minor scratches around and inside grill; dent on the left side of unit below back shelf holder.	\$ 699
COYOTE	C1BIR24-R	23C1BIR24-R16100	24" Outdoor Refrigerator, RH	Rank C: Unit has a line of dents on both sides; multiple scratches to the top and both sides of unit toward bottom left corner and multiple scratches.	\$ 613
COYOTE	CBIR-R	20CBIR-R03895	21" Outdoor Refrigerator, RH	Rank A: Unit has a dent in the back towards the middle and the bottom of unit at the vent.	\$ 600
COYOTE	C1C28NG-FS	20C1C28NGFS10360	28" C-Series Grill w/Cart, 2 Burner, NG	Rank B: Back cart wall is dented.	\$ 599
COYOTE	C1C28NG	9C1C28NG09211	28" C-Series Grill, 2 Burner, NG	Rank A: Small dent on the left side of unit.	\$ 599
COYOTE	C1C28NG	9C1C28NG09210	28" C-Series Grill, 2 Burner, NG	Rank A: Slight dent on the left side of unit.	\$ 599
COYOTE	CBIR-R	6CBIR-R00944	21" Outdoor Refrigerator, RH	Rank B: small dent on the side of the unit open box item	\$ 499
COYOTE	C1PBLP	21C1PBLP03294	Coyote Power Burner, LP	Rank B: Unit has scratches to each corner of the top frame.	\$ 499
COYOTE	CWD	9CWD902	Warming Drawer	Rank B: Slight dent to the front of drawer toward right side of handle.	\$ 499

COYOTE	C1PBLP	22C1PBLP04204	Coyote Power Burner, LP	Rank B: Multiple scratches to the top of the control panel and at the corners of the unit.	\$ 499
COYOTE	C1PBNG	22C1PBNG04299	Coyote Power Burner, NG	Rank B: 2 Dents accompanied by scratches to the top lid.	\$ 499
COYOTE	CBIR-R	21CBIR-R04816	21" Outdoor Refrigerator, RH	Rank A: Unit is dented at the back vent.	\$ 499
COYOTE	C1DBLP	6C1DBLP00218	Coyote Dual Side Burner, LP	Rank A: Minor scratches on the left side of control panel.	\$ 499
COYOTE	CWD	9CWD896	Warming Drawer	Rank C: Scratch and dent to the drawer and slight dent to the drawer at right side of handle.	\$ 399
COYOTE	C1BIR24-L	22C1BIR24-L13941	24" Outdoor Refrigerator, LH	Rank C: Badly dented to the back right corner.	\$ 399
COYOTE	C1DBLP	21C1DBLP01503	Coyote Dual Side Burner, LP	Rank C: Multiple scratches to the top of the item and around the burners.	\$ 299
COYOTE	C1DBLP	21C1DBLP01557	Coyote Dual Side Burner, LP	Rank C: Multiple scratches in noticeable spots on the item.	\$ 299
COYOTE	C1DBLP	21C1DBLP01793	Coyote Dual Side Burner, LP	Rank C: Multiple minor scratches to unit and unit has a dent to front right side of drip tray.	\$ 199
FULGOR MILANO	F6PDF486GS1	Q258780004	48" Sofia Dual Fuel Range, 6 Brass Burners, Griddle	Rank B: Scratch to the top right side of unit; right side of unit has scratches toward the top of unit and scratches to the griddle cover.	\$ 3,999
FULGOR MILANO	F6PGR486GS2	Q353070001	48" Sofia Gas Range, 6 Brass Burners, Griddle	Rank B: Multiple scratches to toe kick	\$ 3,999

FULGOR MILANO	F7PBW24S1-L	F20210201000026	24" Built-In Wine Reserve, Dual Zone, LH, SS	Rank A: Front leveling leg panel dented	\$ 3,999
FULGOR MILANO	F6PIR365S1	Q295790003	36" Sofia Induction Range, 5 Zones	Rank B: Minor scratches to the top of the control panel; dotted line scrapes to the left side of unit; scrape to the upper right side of unit.	\$ 2,999
FULGOR MILANO	F6PIR304S1	Q357660005	30" Sofia Induction Range, 4 Zones	Rank A: Left side panel slightly dented at the front bottom (toe kick) and back bottom.	\$ 2,799
FULGOR MILANO	F6PGR366S2	Q398680008	36" Sofia Gas Range, 6 Brass Burners	Rank B: Dent to the front left of the external range top assembly.	\$ 2,499
FULGOR MILANO	F6PIR304S1	Q386540024	30" Sofia Induction Range, 4 Zones	Rank B: 3 smalll horizontals scratches to the door toward the bottom left corner and scratches to the upper back vent.	\$ 2,499
FULGOR MILANO	F6PDF304S1	Q352570003	30" Sofia Dual Fuel Range, 4 Brass Burners	Rank A: Unit has the left and right bottom corners bent in.	\$ 2,399
FULGOR MILANO	F6PIR365S1	Q393940006	36" Sofia Induction Range, 5 Zones	Rank C: Both side panels slightly dented and unit has scratches to the right side of the control panel and various minor scratches to the front of unit. .	\$ 1,999
FULGOR MILANO	F4PGR366S2	Q377500004	36" Accento Gas Range, 6 Aluminum Burners	Rank A+: Unit is in good condition; Repaired cosmetic damage; No visible damage/	\$ 1,999
FULGOR MILANO	F6FBM36S2	72955475912210002103	36" Freestanding Counter Depth French Door Refrigerator	Rank A: Slight scratcthes to the side of left door toward the top.	\$ 1,999

FULGOR MILANO	F6FBM36S2	72955475912 110050712	36" Freestanding Counter Depth French Door Refrigerator	Rank A: Slight scrape and dent to the left side of unit.	\$ 1,999
FULGOR MILANO	F4PGR366S1	Q353690008	36" Accento Gas Range, 6 Alum Burner, Stainless	Rank A: Left side panel is bent in the back towards the leg. No box	\$ 1,999
FULGOR MILANO	F6FBM36S2	72955475912 210006903	36" Freestanding Counter Depth French Door Refrigerator	Rank A: Good condition	\$ 1,999
FULGOR MILANO	F4PDF304S1	Q393730004	30" Accento Dual Fuel Range, 4 Aluminum Burners	Rank A: Dented on the back bottom left corner of unit.	\$ 1,999
FULGOR MILANO	F4PGR304S2	Q391420011	30" Accento Gas Range, 4 Aluminum Burners	Rank B: Small dent to the top of the control panel towards the right side.	\$ 1,499
FULGOR MILANO	F7SRC36S1-R	F2021102500 0016	36" Built-In Column Refrigerator, Stainless, RH	Rank B: Small dent to the left side of door towards upper handle and a scratch on the right side of the door.	\$ 1,499
FULGOR MILANO	F6PSP30S1	Q439500013	30" Sofia Single Oven, Self Clean, Stainless	Rank A: Dents to the top frame.	\$ 1,499
FULGOR MILANO	F6IRT304S1	Q242120001	30" Professional Induction Rangetop, 4 Zones	Rank B: Minor stains to left side of unit and on top of the control panel.	\$ 999
FULGOR MILANO	F7SCO24S1	Q309750001	24" Combi Convection Steam Oven	Rank A+: Unit is in good condition	\$ 999
FULGOR MILANO	F7SCO24S1	Q397450004	24" Combi Convection Steam Oven	Rank A: Minor scrapes toward the back of frame.	\$ 899
FULGOR MILANO	F6PGK365S1	Q290140019	36" Sofia Gas Cooktop, 5 Brass Burners	Rank A: Good conditon	\$ 799
FULGOR MILANO	F7DSPD24S1	Q427940009	24" Distinto Combi Convection Speed Oven	Rank B: Multiple dents to the top and back frame of unit.	\$ 699
FULGOR MILANO	F7SP30S1	Q317840004	30" 700 Series Convection Single Oven, Self Clean	Rank C: Slightly used and in great condition.	\$ 499
FULGOR MILANO	F6DWT24SS2	2080016508	24" Sofia Dishwasher, 3-Rack, Stainless	Rank B: Unit has dents on the bottom of the stainless steel door.	\$ 499

FULGOR MILANO	F1SM30S1	Q352660012	30" Single Euro Height Oven, Easy Clean, Convection, 100 Series	Rank A: Unit is in good condition.	\$ 499
FULGOR MILANO	F1SP24S2	Q243160002	24" Single Oven, Self Clean, Convection, 100 Series	Rank B: Scratch to the handle and scrapes to the top of unit.	\$ 399
FULGOR MILANO	F6DWT24SS2	2180090409	24" Sofia Dishwasher, 3-Rack, Stainless	Rank A+: Good condition; Replaced door panel; No noticeable cosmetic damage.	\$ 399
FULGOR MILANO	F1SM30S1	Q333020022	30" Single Euro Height Oven, Easy Clean, Convection, 100 Series	Rank A: Unit has a big dent on the front left corner behind the front trim.	\$ 399
FULGOR MILANO	F4DWS18FI1	04758499003 795060023	18" 400 Series ADA Dishwasher, Panel Ready	Rank A: DENTED TOWARD THE BOTTOM OF THE DOOR	\$ 399
PERLICK	H80CIMW	M00446C	15" Cubelet Ice Maker, Panel Ready, Hinge Reversible	Rank A: Dent to the top lid towards the right side and slight dent towards the back of lid and various minor scratches to the top.	\$ 2,999
PERLICK	HP24TO-4-1R-2	2107020030B	24" SigSeries BeerDisp OD, SS Solid Door, RH 2 Tap	Rank A: Dent on left side, will be hidden once installed. Has original wrapping. In GREAT shape!	\$ 2,699
PERLICK	HP24WS-4-3R	2204010125B	24" SigSeries Wine Res, SS Glass Door, RH	Rank A: Dent and scratch to the top of unit on the left side.	\$ 2,599
PERLICK	H80CIMS-R	N10707H	15" Cubelet Ice Maker, SS Solid Door, RH	TOP LEFT CORNER OF DOOR DENT/DING	\$ 2,499
PERLICK	H80CIMS-ADL	L20147L	15" ADA Cubelet Ice Maker, SS Solid Door, LH	Rank A: Top right side slightly bowed out.	\$ 2,499
PERLICK	H80CIMS-ADL	M00168C	15" ADA Cubelet Ice Maker, SS Solid Door, LH	Rank A: Slight dents in both right and left panels and the lid is slightly bowed out due to the small dent at the back right corner of unit.	\$ 2,499

PERLICK	HC24TB-4-2L-2	2203150059b	24" C-Series BeerDisp, FI Solid Door, LH, 2 Tap	Rank A: Minor scratches to the top of unit.	\$ 2,499
PERLICK	HC24TB-4-1R-2	2201260093B	24" C-Series BeerDisp, SS Solid Door, RH, 2 Tap	Rank A: Minor scratches to the top of the unit.	\$ 2,499
PERLICK	H50IMW	M11364K	15" Clear Ice Maker, FI Solid Door	Rank A: Back bottom vent dented on the right side; Minor scratches to the top of unit; Small scrape on the left side of unit.	\$ 2,499
PERLICK	H50IMW	L00696K	15" Clear Ice Maker, FI Solid Door	Rank A: Unit is dented on the left side toward the front foot.	\$ 2,499
PERLICK	HP24RO-4-1RL	2205160070B	24" SigSeries Refrig, OD, SS Solid Door, RH, w/Lock	Rank A: Slight dent to the back vent near lower right corner.	\$ 2,299
PERLICK	HP24BO-4-2L	2205020019B	24" SigSeries BevCenter, OD, FI Solid Door, LH	Rank A: Unit is in good condition.	\$ 2,199
PERLICK	HP24FS-3-5	2005183175B	24" SigSeries Freezer, SS Drawers	Rank A: Front bottom corners are bent and the whole back grill on the bottom is bent.	\$ 2,199
PERLICK	H80CIMS-ADR	M00201F	15" ADA Cubelet Ice Maker, SS Solid Door, RH	Rank C: Unit has multiple dents to the lid and multiple minor dents to the door; dent to the top of door at the left corner.	\$ 1,999
PERLICK	HP24RM-4-5	2210260052b	24" Signature Series Marine Grade Refrigerators, SS Drawers	Rank C: Bad dent to the top back right corner and slight dent to the back vent at bottom right corner.	\$ 1,999
PERLICK	HC24TB-3-2R2	2007167655B	24" C-Series BeerDisp, FI Solid Door, RH, 2 Tap	Rank B: Unit has dents on the lower left and right side panels and is missing the toe kick.	\$ 1,999

PERLICK	H50IMW	M01215C	15" Clear Ice Maker, FI Solid Door	Rank B: Dented at the back right corner and the lid is bowed out on the right side.	\$ 1,999
PERLICK	HA24RB-4-6	2204040088B	24" ADA Refrig, FI Overlay Drawers	Rank B: Dent on the left side of unit towards the back; On the back of unit the upper left corner frame is bent slightly outward.	\$ 1,999
PERLICK	H50IMW	M01116C	15" Clear Ice Maker, FI Solid Door	Rank A+: Small dent to the top left corner of the door.	\$ 1,999
PERLICK	HA24RB-4-3R	2307210084B	24" ADA Refrig, SS Glass Door, RH	Rank A: Unit is slightly bowed out on both sides of the toe kick.	\$ 1,999
PERLICK	H50IMS-R	L02896J	15" Clear Ice Maker, Indoor/Outdoor, SS Solid Door, RH	Rank A: Small dent and light scratch to the lid of unit.	\$ 1,999
PERLICK	HP24FO-3-1L	2011030040B	24" Freezer, Outdoor, SS Solid Door, LH	Rank A: Scrapes on both sides and on top of unit.	\$ 1,999
PERLICK	HH24BS-4-4L	2204280028B	24" Sottile ShDpth BevCenter, FI Glass Door, LH	Rank A: Multiple scratches to the top of unit.	\$ 1,999
PERLICK	H50IMS-ADL	M07198A	15" ADA Clear Ice Maker, SS Solid Door, LH	Rank A: Multiple dents and scratches to the top of the lid.	\$ 1,999
PERLICK	HP24FO-4-2L	2106030076B	24" Freezer, Outdoor, FI Solid Door, LH	Rank A: Dent toward back right corner.	\$ 1,999
PERLICK	H50IMS-R	L02707F	15" Clear Ice Maker, Indoor/Outdoor, SS Solid Door, RH	Rank A: Top lid has a slight outward bend on the right side; Slight dent to the back corner.	\$ 1,999
PERLICK	H50IMW	L00435C	15" Clear Ice Maker, FI Solid Door	Rank A: Dents on the side and all along the top of the unit.	\$ 1,999
PERLICK	HP24RS-4-4L	2107220090B	24" SigSeries Refrig, FI Glass Door, LH	Rank A: Small dent and scratches to the top of unit.	\$ 1,899
PERLICK	H50IMS-ADR	K15126F	15" ADA Clear Ice Maker, SS Solid Door, RH	Rank A: Scratch and dent to the right side of unit.	\$ 1,899

PERLICK	HP15WS-4-3R	2106080012B	15" SigSeries Wine Res, SS Glass Door, RH	Rank A: Dented on the top left side toward the middle of unit.	\$ 1,899
PERLICK	HA24RB-4-2L	2205110094B	24" ADA Refrig, FI Solid Door, LH	Rank U: #Rank B: Dented at the back left corner of unit.	\$ 1,699
PERLICK	HC24BB-4-3R	2110150081B	24" C-Series BevCenter, SS Glass Door, RH	Rank A: Minor scrape and scratch to the back of the top of unit.	\$ 1,699
PERLICK	H50IMS-R	N03732C	15" Clear Ice Maker, Indoor/Outdoor, SS Solid Door, RH	Rank C: door dented	\$ 1,499
PERLICK	H50IMW	N11701J	15" Clear Ice Maker, FI Solid Door	Rank C: damage to the top hinge and vent panel on the back is pushed in	\$ 1,499
PERLICK	HP24FS-4-1R	2211160043B	24" Freezer, SS Solid Door, RH	Rank C: Badly dented at right back corner.	\$ 1,499
PERLICK	HA24FB-3-1L	2008280043B	24" ADA Freezer, SS Solid Door, LH	Rank B: Unit does not have laser film on it; The stainless steel door has some type of water stain that does not seem to come off when cleaned; The top right side of the unit has a deep scratch on it; The bottom grill in the back has a dent on it.	\$ 1,499
PERLICK	H50IMS-R	L02651D	15" Clear Ice Maker, Indoor/Outdoor, SS Solid Door, RH	Rank B: Slight dent to top front right corner; scratches to the top; scratch and dent to left side; dent to the right side of unit.	\$ 1,499
PERLICK	HA24BB-4-1R	2201120047B	24" ADA BevCenter, SS Solid Door, RH	Rank A: Slight dent to the back left corner.	\$ 1,499
PERLICK	H50IMW	K10192J	15" Clear Ice Maker, FI Solid Door	Rank A: Light scratches to the top of the unit.	\$ 1,499

PERLICK	HA24RB-3-1L	2009047606B	24" ADA Refrig, SS Solid Door, LH	Rank A: Dented on the top toward the back right corner	\$ 1,499
PERLICK	HC24BB-4-2R	2110150020B	24" C-Series BevCenter, FI Solid Door, RH	Rank A: Deep scratch on the left side of unit.	\$ 1,499
PERLICK	H50IMS-L	N15057F	15" Clear Ice Maker, Indoor/Outdoor, SS Solid Door, LH	C; dent to right side, scratches on handle	\$ 1,499
PERLICK	HH24RS-4-3R	2210100030B	24" Sottile ShDpth Refrig, SS Glass Door, RH	Rank C: Back right corner smashed in causing a dent on the right side of unit and top of unit.	\$ 999
PERLICK	HA24BB-3-2L	2009300104B	24" ADA BevCenter, FI Solid Door, LH	Rank B: Unit has a big dent in the back upper right hand corner.	\$ 999
ZIP WATER	01038399	2021020551089	Boiling, Chilled, Sparkling Kit Unit, 120V, CO2, Regulator (BCS120V-1)	Rank B: small dents to sides of unit	\$ 1,999
ZIP WATER	01037423	2021113051108	Boiling, Chilled, Sparkling Unit, 120V, w/o Regulator or Co2	Rank B: Inner frame on left side toward the back is slightly dented causing back panel to be unlevel; Frame slightly distorted causing back panel to not be aligned with the unit.	\$ 1,999
ZIP WATER	01037423	2022030951084	Boiling, Chilled, Sparkling Unit, 120V, w/o Regulator or Co2	Rank A: Slight bump to the top of unit.	\$ 1,999